	rjngroup	City of Baltimore - Bureau of Water and Wastewater									Site Name	
	and the second s			low Monitoring Services for Sanitary Sewer Sy					City MH I.D.			
	Sewershed	Projec	t No.	_	ection Date/I			-				
	PATAPSCO		005	D		/30/06 16:30				002MH		
	PATAPSCO	995R		)K			Inspected By		hole		ipe	
	Site Address: 173			atapsco Av	ve (in field to	JM / ED north)		Depth (ft) 11.35	Width (ft) 4.50	Width (in) 42.00	Height (in) 42.00	
					Brick Oconcrete Clay Other			Pipe Shape:	O Circular	○ Box	● Odd	
	Top View Picture				Area Location Map				Safety Concerns			
PART A - SITE INVESTIGATION	Area View Picture  Area View Picture					Vicinity Ma		Stonehouse Cove	Gas ☐ Traffic  ✓ Access ☐ Other   Meter Location  ● U/S ○ D/S ☐ I ft  Manhole Coordinates  570,736.16 N 1,430,520.34 W  Telog Antenna Installation ☐ Asphalt ☑ Soil ☐ Concrete ☐ Traffic Signal Strength 50%  Telog Phone # (443) 844-2367  System Characteristics ☐ Residential ☑ Commercial ☐ Industrial			
	Hydraulic Assessment											
	Surcharge (ft): 9.00 ☑ Straight ☐ Bend ☐ Drop Inlet ☐ Backwater ☐ Pump Sta. ☐ WWTP ☐ Needs Cleani										s Cleaning	
	Flow Depth (in): 10.50 Instant Vel (fps): 3.00 Silt Level (in): 0.00 Signs of I/I: Wall / Pipe									e		
	HYDRAULIC RATING:					onable) C (poor)			Recomme		Yes   No	
									Meter Ty	pe: ADS: F	lowShark	
	Installation Plan Sketch							Installation	Profile Sketcl	1		
PART B - SITE INSTALLATION	42.00"					U					FARI B. SILE INSTALLATION	
NST	Installation Information					,			Installation	on Photo	į.	
TEI		1	Incon		I	Outgoing	OF	-			Z Z	
-SI	Line #	1	2	3	4	1 42.00	1		of a little	1	A	
TB	Size (in)	m				42.00 Other					A	
PAR	Material  Debris (Y/N)	e t				N		1				
	Shape	e				Odd		01/1				
	Flow Depth (in):	r				10.50						
	Instant. Vel. (fps)	·				3.00		1.1				
	Comments: Could not replace manhole cover. Site needs ring and							11				
	cover from City											
	Clay Tile Lining.									X /		